

# Your Loft

2091 Goetz Rd.  
Perris, CA 92570  
(951) 657-2676  
Email: yourloft@yahoo.com

## MAIN CANOPY INSPECTION FORM

Owner: Bill Morrison

Inspected by: [Signature] Date: 3/26/17

Canopy Type: Blade 108

Serial #: ?? DOM: ??

INSPECTION - Scale 1-5: 1=Un-airworthy, 2=Needs Repair, 3=O.K., 4=Good, 5=Excellent

Risers N/A ( ) type 8.....( ) type 17.....length.....

Toggles N/A ( ) type:.....

Bridle N/A ( ) Length.....

D-bag N/A ( ) standard.....( ) semi-stow less.....( ) stow - less.....

Pilot chute N/A ( ) collapsible.....( ) non-collapsible.....( ) size.....

Links (3) soft.....( ) hard.....Bumpers... Yes.....No.....

Lines ( ) spectra.....( ) vectran.....( ) dacron.....(4) HMA.....( ) other.....

Slider ~~(3)~~ (2) collapsible.....( ) non-collapsible.....( ) other.....

Stabilizers (4).....

Bridal Attachment:

Top (4).....

I Beam (4).....

Bottom (4).....

Top Skin (4).....

Ribs (4).....

Cross Ports (3) Normal FRAY around Xports & winglet intake

Bottom Skin (4).....

Trim:

A-B (4).....A-C (4).....A-D (4).....A-Brakes (4).....Brake-Toggle (4).....

Comments:

All 4 slider Cornets are worn/