

# HARNESS AND CONTAINER INSPECTION FORM

Owner: Bill Morrison

Inspected by: [Signature] Date: 3/26/17

Container Type: Team Sport I4

Serial #: 251206 DOM: 02/2005

INSPECTION - Scale 1-5: 1=Un-airworthy, 2=Needs Repair, 3=O.K., 4=Good, 5=Excellent

## HARNESS:

Stitching (3)

Hardware (3) type:

Housings (3) type:

Main Lift Web (3) type: Slight Color Fade Due to Age

Chest & Leg Straps (3) wear points on hip rings over stitch leg straps  
minor wear leg pads

## CONTAINER:

Stitching (3) minor over stitch

Fabric (3) type:

Flap Plastic (3)

Velcro (3)

P/C Pocket (5) type: new

Grommets (3)

Ripcord (5) type: soft

Cutaway Handle (3)

Reserve Toggles (3)

Freebag & Bridle (3)

Safety Stow (3)

Reserve P/C (3)

RSL N/A

AAD ( ) type: Cypres Due 09/17

Main Risers (4) type: 17

Main D-Bag (3)

Main Bridle (3)

Main P/C (3)

Comments:

Your Loft  
2091 Goetz Rd.  
Perris, CA 92570  
(951) 657-2676

RESERVE CANOPY INSPECTION FORM

Owner: Bill Harrison

Inspected by: [Signature] Date: 3/27/17

Canopy Type: Aerodyne SMART 150

Serial #: 251083 DOM: 02/05

INSPECTION - Scale 1-5: 1=Un-airworthy, 2=Needs Repair, 3=O.K., 4=Good, 5=Excellent

Free-bag (4) line stow elastic stretching

Safety Stow (4)

Bridle (4)

Pilot chute (4)

( ) Above Items already inspected on Harness & Container Form

Links (4) type: Soft

Lines (4) type: Spectra

Slider (4) type:

Stabilizers (4)

Bridal Attachment:

Top NA

I Beam NA

Bottom NA

Top Skin (4)

Ribs (4)

Cross Ports (4)

Bottom Skin (4)

Trim:

A-B (4) A-C (4) A-D (4) A-Brakes (4) Brake-Toggle (4)

Comments:

small stain left rose cell -  
27 documented pack cycles three actual deployments  
records since day one - very good - excellent condition